



Wireless Gaming Mouse


AORUS M6

Quick
Guide


GETTING STARTED

- Please fully charge your mouse before using it for the first time.
- A depleted battery will be fully charged in approximately 3 hours.
- If your mouse has not been used for an extended period, you may need to recharge it before use.
- The mouse requires a USB connection that can supply sufficient power to charge the battery, and this connection also acts as the wired mode for your mouse.
- When charging begins after the charging cable is connected, the DPI indicator will show a static green light for 5 seconds.

How to activate the mouse?



How to charge the battery?



DPI indicator

Battery Percentage	DPI indicator Effect
<5%	Flashing red light continuously
<10%	Flashing red light for 5 seconds
<20%	Flashing red light for 5 seconds
20%-99%	No effect
100%	Static Green light (In charging mode)

- You can view more detailed battery status through the GIGABYTE Control Center.

DPI	DPI indicator light
800(Default)	White
1600	Yellow
3200	Cyan
6400	Magenta

- You can change your mouse's DPI to match your playstyle with a press of the DPI cycle button or fine-tune your own sensitivity setting using the GIGABYTE Control Center.