

INSTRUCTIONS FOR REPROGRAMMING FINDER TIME SWITCHES 12 SERIES IN CASE OF DATE MISALIGNMENT

To enable the correct operation of the inserted automation, it is possible to **reprogramming the Types 12.51, 12.6x, and 12.Ax** time switches only if configured in weekly programming.

Below are the **STEPS** for reprogramming:

- ✓ in **March 2024** change the year of the device to 2019;
- ✓ from the **1st of April to the 31st of December 2024** the year must be set back to the current one (2024).


If no action is taken, the date will align itself on the 1st of April 2024 (the misalignment during March 2024 will be still an issue).

HOW TO SET THE YEAR 2019 VIA FINDER TOOLBOX APP

By updating the **Finder Toolbox app**, simply **send the date and time** to set the year automatically to 2019.


From the 1st of April to the 31st of December 2024, the current year must be set back to the current one (2024) by sending the date and time again.

N.B.: This condition will **NOT** repeat every leap year.




HOW TO SET THE YEAR 2019 MANUALLY


TIME SWITCHES TYPE 12.A1 - 12.A2



TIME SWITCH TYPE 12.A4



TIME SWITCH TYPE 12.51



TIME SWITCHES TYPE 12.61 - 12.62

