



Release Notes – Zebra Android 14

14-38-04.00-UG-U00-STD-HEL-04 Release (GMS)

Highlights

This Android 14 GMS release covers MC20, RZ-H271, CC600, CC6000, EC30, EC50, ET51, L10A, MC2200*, MC2700*, MC9300, TC21, TC21 HC, TC26, TC26 HC, TC52, TC52 HC, TC52x, TC52x HC, TC52AX, TC52AX HC, TC57, TC57x, TC72, TC77, TC8300, MC3300ax, MC3300x, MC3300xR, VC8300 & WT6300 family of products.

***Please find the special note for MC2200/MC2700 for A14 release support.**

Hardware	2GB/16GB(BG)	3GB/32GB w/o Camera (MG)	3GB/32GB With Camera (PG)
MC2200	No support	Supported	Supported
MC2700	No support	SKU Unavailable	Supported

Starting at Android 11, Delta Updates must be installed in sequential order (ascending oldest to newest); Update Package List (UPL) is no longer a supported method. In place of installing multiple sequential Deltas, a Full Update can be used to jump to any available LifeGuard Update.

LifeGuard patches include all previous fixes that are part of earlier patch releases.

Please see, device compatibility under Addendum Section for more details.

AVOID DATA LOSS WHEN UPDATING TO ANDROID 14
Read <https://techdocs.zebra.com/lifeguard/a14/> SDM660 Upgrade Path on TechDocs

Software Packages

Package Name	Description
HE_FULL_UPDATE_14-38-04.00-UG-U00-STD-HEL-04.zip	Full package update
HE_DELTA_UPDATE_14-35-10.00-UG-U04-STD_TO_14-38-04.00-UG-U00-STD.zip	Delta package from previous release 14-35-10.00-UG-U04-STD
Releasekey_A14_EnterpriseReset_V1.zip	Reset Package to Erase User Data Partition Only
Releasekey_A14_FactoryReset_V1.zip	Reset Package to Erase User Data and Enterprise Partitions

Zebra Conversion Package for migrating to Android 13 or Higher without data loss

- SD660 upgrades to A13 or A14 from lower OS dessert causes a data reset due to encryption updates. The ZCP is released to do perform selective data persistence during the upgrade process. This process is explained in the techdocs. <https://techdocs.zebra.com/lifeguard/a13/>.
- If there is a requirement to configure a PIN, Pattern or Password policies post migration to Android 13 or Android 14, then Admin must send a Password Reset (with a NULL or Empty password value) via EMM console. After this mandatory step the Admin can proceed with configuring the required PIN, Pattern or Password policies on device.
- The ZCP OS will be released in cadence with A11 LG releases to make sure it is based on the latest Security patches as per the Zebra security team guidelines.
- **The correct ZCP OS needs to be selected based on the current source BSP on the device being upgraded as mentioned in the table below.**

Current Source OS Versions present on device			* Zebra Conversion Package to be used	Notes
OS Dessert	Release Date	Build Version		
Oreo	Any Oreo release	Any Oreo release	11-99-99.00-RG-U547-STD-HEL-04	Android Oreo - For devices with LG version earlier than 01-23-18.00-OG-U15-STD, the device must be upgraded to this version or newer prior to beginning the migration process.
Oreo	December 2024 release	LIFEGUARD UPDATE 01-83-27.00-OG-U00 (Dec 2024)	11-99-99.00-RG-U576-STD-HEL-04	TC77, TC57 and TC57X new Power Amplifier devices (Hardware Ver SKY77652) will not be allowed to use U547, U556 and U566 BUILDS.
Oreo	September 2025 release	LIFEGUARD UPDATE 01-94-19.00-OG-U00 (Sept 2025)	11-99-99.00-RG-U590-STD-HEL-04	Devices having property ro.custom.config.device.wifi.srcc as value 14 will not be allowed to use U547, U556, U566, U576 and U586 BUILDS.
Pie	Any Pie release	Any Pie release	11-99-99.00-RG-U547-STD-HEL-04	For Android Pie, the device must be upgraded to Android 10 or 11 to begin the migration process.
A10	Any A10 release	Any A10 release	11-99-99.00-RG-U547-STD-HEL-04	All versions supported for migration to A13 or higher.
A10	October 2024 release	LIFEGUARD UPDATE 10-63-19.00-QG-U00 (Oct 2024)	11-99-99.00-RG-U566-STD-HEL-04	PS20 and MC3300x new display devices will not be allowed to use U547 and U556 BUILDS.

A10	November 2024 release	LIFEGUARD UPDATE 10-63-18.00-QG-U00 (Nov 2024)	11-99-99.00-RG-U576-STD-HEL-04	TC77, TC57 and TC57X new Power Amplifier devices (Hardware Ver SKY77652) will not be allowed to use U547, U556 and U566 BUILDS.
A10	September 2025 release	LIFEGUARD UPDATE 10-74-20.00-QG-U00 (Sept 2025)	11-99-99.00-RG-U590-STD-HEL-04	Devices having property ro.custom.config.device.wifi.srrc as value 14 will not be allowed to use U547, U556, U566, U576 and U586 BUILDS.
A11	May 2023 To January 2024 release	From LIFEGUARD UPDATE 11-35-05.00-RG-U00 (May 2023) till 11-42-18.00-RG-U00 (January 2024)	11-99-99.00-RG-U547-STD-HEL-04	
A11	April 2024 release	LIFEGUARD UPDATE 11-46-25.00-RG-U00 (April 2024)	11-99-99.00-RG-U556-STD-HEL-04	
A11	July 2024 release	LIFEGUARD UPDATE 11-49-09.00-RG-U00 (July 2024)	11-99-99.00-RG-U566-STD-HEL-04	PS20 and VC83-10 inch new display devices will not be allowed to use U547 and U556 BUILDS.
A11	Dec 2024 to Jan 2025 release	From LIFEGUARD UPDATE 11-54-19.00-RG-U00 (Dec 2024) to 11-54-26-RG-U00 (Jan 2025)	11-99-99.00-RG-U576-STD-HEL-04	TC77, TC57 and TC57X new Power Amplifier devices (Hardware Ver SKY77652) will not be allowed to use U547, U556 and U566 BUILDS.
A11	April 2025 release	LIFEGUARD UPDATE 11-58-08.00-RG-U00 (April 2025)	11-99-99.00-RG-U586-STD-HEL-04	
A11	July 2025 release	LIFEGUARD UPDATE 11-61-11.00-RG-U00 (July 2025)	11-99-99.00-RG-U590-STD-HEL-04	Devices having property ro.custom.config.device.wifi.srrc as value 14 will not be allowed to use U547, U556, U566, U576 and U586 BUILDS.

Security Updates

This build is Compliant up to [Android Security Bulletin](#) of February 01, 2026.

LifeGuard Update 14-38-04.00-UG-U00

- LifeGuard Update 14-38-04.00-UG-U00 contains security updates and bug fixes.
- This LG Delta Update package is applicable for 14-35-10.00-UG-U04-STD-HEL-04 BSP version.

- **New Features**

- **OSX**

- Added enhancement to UI Manager Clipboard share feature to block clipboard overlay when Clipboard share is disabled
- Added a feature to block access to AppInfo for specific applications in Android Settings panel.
- **Scanner Framework**
 - Auto Illumination in Camera Scanning: Adds a new “Auto” illumination mode in DataWedge camera scanning that automatically turns on the torch in low light environments to improve scan reliability.
 - Imager (Scan Engine) Frames Streaming: Introduces the new Imager Frames Streaming workflow in DataWedge, enabling applications to request and receive multiple images directly from the imager (scan engine).
- **WWAN**
 - Smart(e)sim feature support added.
- **Event Injection Service**
 - The Zebra Event Injection Service now supports Android Direct Boot, which allows remote control sessions while the device lock screen is displayed.
- **Resolved Issues**
 - SPR56150 - Resolved an issue wherein the APN was not getting updated as it was non-editable.
 - SPR58500 - Resolved an issue wherein the SEND CHAR was being appended at the end.
 - SPR58166 - Resolved an issue wherein the BT scanner connection/disconnection toast messages were not working.
 - SPR55789 - Fixed an issue where in auto rotate feature stopped working after downgrading the device to sensor unsupported BSP.
 - SPR58271 - OEMCONFIG support was added for AOSP devices.
 - SPR58427 - Resolved an issue wherein scanner stops working.
 - SPR58004 -Resolve an issue wherein scanning would stop decoding after some duration when using Presentation Mode.
 - SPR58232 - Resolved an issue wherein DW RFID input plugin would go missing when device was connected with RFD40 via eConnex.
 - SPR58291 - Resolved an issue wherein adding an APN via OEMConfig was not possible when using the SOTI MobiControl EMM.
 - SPR58433 - Resolved an issue wherein device was unable to decode Google wallet QR code.
 - SPR58279 - Resolved an issue wherein free form image capture was taking more time.
 - SPR58443 - Resolved an issue wherein Rxlogger was not reporting correct CPU Temp.
 - SPR58746 - Resolved an issue where Gboard failed to minimize automatically when using the Zebra physical keypad.
 - SPR58944 - Resolved an issue wherein device was unable to connect to AT&T data after updating to A14.
 - SPR59213 - Resolved an issue wherein users were unable to unlock the device after migrating from A11 to A14 via ZCP.
 - SPR58847 - Resolved an issue wherein App whitelisting using AccessMgr was not working as expected when applock was enabled
 - SPR58538 - Resolved an issue wherein the navigation bar was soft keys were not working after an Enterprise reset.

- SPR57718 - Improved to ensure that enrollment notifications are displayed only when the token is validated and the enrollment process started.
- SPR59024 – Resolved an issue wherein Orange Belgium APN is added.

- **Usage Notes**

- **Setup Wizard Bypass Enhancements:**

- Staging can now be initiated from the Welcome (“Hi there”) screen by scanning a StageNow barcode or applying a staging (.bin) file from a USB/SD card. This action reduces the number of Google-mandated manual interactions to three, after which StageNow automatically launches to allow provisioning to continue. This is also applicable when scanning an enrollment barcode for Zebra DNA Cloud and compatible EMM systems. For more details, please refer to the Zebra documentation:

<https://techdocs.zebra.com/stagenow/latest/profiles/wipedevice/#setupwizardbypass>

LifeGuard Update 14-35-10.00-UG-U04

- LifeGuard Update 14-35-10.00-UG-U04 contains security updates.
- This LG Delta Update package is applicable for 14-35-10.00-UG-U02-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-35-10.00-UG-U02

- LifeGuard Update 14-35-10.00-UG-U02 contains security updates.
- This LG Delta Update package is applicable for 14-35-10.00-UG-U00-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-35-10.00-UG-U00

- LifeGuard Update 14-35-10.00-UG-U00 contains security updates and bug fixes.
- This LG Delta Update package is applicable for 14-32-12.00-UG-U06-STD-HEL-04 BSP version.

○ **New Features**

○ **MX 15.0**

- **Access Manager** adds the ability to:
 - Enter the Class Name of a [derived Accessibility Service class](#) to receive permission for use. This access level can be granted only to apps with Device Owner status.
- **License Manager** adds the ability to:
 - Select whether to [limit the licensing app](#) to read-only, which blocks the device user from performing licensing actions and making changes to configuration settings.
 - Enter the [on-device path](#) of the lservrc offline software license file.

○ **Wireless Analyzer**

- Dynamic BW feature significantly improves the accuracy of Fine Timing Measurement (FTM) when operating in lower bandwidths of 20 MHz and 40 MHz. With this enhancement, clients operating in these lower bandwidths will now experience accuracy levels comparable to those achieved in the 80 MHz bandwidth, ensuring consistent and reliable performance across varying bandwidth conditions.

○ **Scanner Framework**

- Included SE55 Firmware PAAFNS00-002-R04.
- Added security levels for Codabar barcode.
- SNAPI Image Brightness, SNAPI Image Quality, SNAPI Image Enhancement parameter configurations are added for SNAPI USB Scanner.
- Added parameters support for Zebra USB Scanner (SNAPI).
- Added support for RFD90 scanner via Zebra USB Scanner option.

○ **Workstation Connect**

- Workstation Connect is now supported on this release, for details on compatibility please check [workstation-connect](#).

○ **WLAN**

- Added support for Auto time configuration with Aruba infrastructure.

○ **Battery**

- Added support for French (Canada) translation/localization for Battery Swap options.

○ **OSX**

- Added support to disable Large-Screen Taskbar permanently based on a custom system property.
- **Security enhancements to MxMS subsystem**
 - Users of SSM are encouraged to deploy this update to ensure future compatibility.
- **Resolved Issues**
 - SPR57585 - This update resolves connection issues when using BT HID mode via the BT Pairing Utility, ensuring users can seamlessly connect their scanners to devices in Bluetooth HID mode.
 - SPR48678 - This fix ensures that logging operates properly even when USB restrictions are in place. By enabling effective logging, it allows administrators and support teams to capture diagnostic data for troubleshooting and resolving device issues.
 - SPR57292 - This update addresses scenarios where devices may fail to switch to WLAN when WWAN connectivity is lost. With this fix, devices now transition seamlessly to WLAN, ensuring uninterrupted connectivity.
 - SPR57132 - This fix ensures the scan beep sounds are consistently played on successful barcode decodes, providing clear audio feedback to users.
 - SPR56364 - This update improves the reliability of OCR decoding for specific use cases, such as reading manufacturing year details on tires. This update improves the reliability of OCR decoding for specific use cases, such as reading text on tires.
 - SPR57792 - This fix resolves connection stability issues with the RFD40 accessory, ensuring consistent pairing even after suspend/resume operations.
 - SPR57221 - This update ensures that TC57x devices are fully compatible with T-Mobile CZ's VoLTE and MMI call services.
 - SPR55645 - This fix optimizes the size of the back button to reduce accidental touches that could disrupt workflows.
 - SPR57199 - This update ensures that EMM administrators receive accurate status for OS upgrades in their management consoles.
 - SPR56399 - This fix enables users to perform seamless firmware updates for external USB scanners using their mobile computers.
 - SPR56511 - This update increases the RxLogger Logcat buffer size and allows users to apply more than 32 filters for log management. This update increases the RxLogger Logcat buffer size so that support teams capture more events when troubleshooting.
- **Usage Notes**
 - None

LifeGuard Update 14-32-12.00-UG-U06

- LifeGuard Update 14-32-12.00-UG-U06 contains security updates.
- This LG Delta Update package is applicable for 14-32-12.00-UG-U03-STD-HEL-04 BSP version.

- **New Features**
 - None
- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-32-12.00-UG-U03

- LifeGuard Update 14-32-12.00-UG-U03 contains security updates.
- This LG Delta Update package is applicable for 14-32-12.00-UG-U00-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-32-12.00-UG-U00

- LifeGuard Update 14-32-12.00-UG-U00 contains security updates and bug fixes.
- This LG Delta Update package is applicable for 14-28-15.00-UG-U05-STD-HEL-04 BSP version.

- **New Features**

- **MX 14.2**

- Access Manager adds to:
 - Access Permissions the ability to use Android "exact alarm" APIs and to read (and optionally write) Android systems settings.
- Audio Volume UI Manager adds the ability to:
 - Enable/Disable Mute state control by the device user.
 - Enable/Disable Vibrate state control by the device user.

- **Wireless Analyzer**

- The trial license for Wireless Insight period changed from 1 year to 6 months.

- **Scanner Framework**

- Added support for MP7000 scanner
- Included support for FS40 scanner

- **Zebra License Manager Zebra Applications**

- Zlicensemgr application v15.0.4.5.0.3 with Badge ID activation, LLS, and offline bin file support has been integrated.

- **Resolved Issues**
 - SPR56024 - Resolved an issue wherein the device date and time would reset to default date/time upon battery removal for 20sec before insertion.
 - SPR51276 - Resolved an issue wherein audio was not heard during speaker phone call.
 - SPR56712 - Resolved an issue wherein WIFI disconnection was observed due to NCC settings being enabled by default by OEMConfig.
 - SPR56187 - Resolved an issue wherein scrolling is not smooth in Stylus, Glove and Finger mode.
 - SPR56574 - Resolved an issue wherein Recent apps were not working in SOTI lockdown mode.
 - SPR56634 - Resolved an issue wherein the notification bar could still be accessed via long press of power button menu even though it was disabled by Mx.
 - SPR56181 - Telephony Manager Custom Feature CSP support has been added.
 - SPR56770 - Resolved an issue wherein the OCR output incorrectly used a comma instead of a period in numeric values.
 - SPR56086 - Resolved an issue wherein Japanese text on the StageNow top screen was cut off and could not be fully viewed.
 - SPR56429 - Resolved an issue wherein the NFC app would crash on TC57 and TC77 device models running Android 14 when unlocking the screen to resume tasks.
 - SPR56941 - Resolved an issue wherein activation and staging failed when the device language was set to Japanese.
 - SPR57068 - Resolved an issue wherein OS updates on WS50 devices failed during installation via SOTI due to an exception in the MX proxy framework.
 - SPR56642 - Resolved an issue wherein DataWedge RFID input failed to output ASCII from the User Memory Bank when Hex to ASCII was enabled.
 - SPR56610 - Resolved an issue wherein Wi-Fi would randomly turn off and Airplane mode would activate unexpectedly.
 - SPR56163 - Resolved an issue wherein intermittent errors occurred while accessing web pages due to proxy service disruptions.
 - SPR56352 - We have fixed the issue where the Touch and Hold delay functionality was not working in MX13.5.
 - SPR56084 - Resolved StageNow default log path is different from A13.
 - SPR56195 - Resolved AppMgr was not able to install xapks.
 - SPR56104 - Resolved CertMgrMgr was throwing error on installing .crt certificates.
 - SPR-53808 - Resolved an issue where in few devices were unable to scan enhanced dot data matrix labels consistently.
 - SPR57753 - Added support to allow an app to update system settings.
 - SPR55523 - Updated firmware PAAFNS00-002-R03 for SE55 Scan Engine with enhancements which will improve system performance and address minor occurrences of memory corruption. This update is highly recommended.
 - SPR57604/SPR57761 - Resolved an issue wherein Enterprise Browser v5.0.0.13 - Randomly displaying 'Device clock check failed'.
 - SPR57733 - Resolved an issue wherein Device guardian would request permissions while installing from playstore.
 - SPR56019 - Resolved an issue wherein changing the language to Turkish, restarting the device, and then pressing the Alpha Key (Orange key) would cause problems when attempting to type the letters 'D' and 'R'.
 - SPR56186 - Resolved as issue wherein pressing a physical key produces sound twice.

- **Usage Notes**

- None

LifeGuard Update 14-28-15.00-UG-U05

- LifeGuard Update 14-28-15.00-UG-U05 contains security updates.
- This LG Delta Update package is applicable for 14-28-15.00-UG-U03-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-28-15.00-UG-U03

- LifeGuard Update 14-28-15.00-UG-U03 contains security updates.
- This LG Delta Update package is applicable for 14-28-15.00-UG-U00-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-28-15.00-UG-U00

- LifeGuard Update 14-28-15.00-UG-U00 contains security updates and bug fixes.
- This LG Delta Update package is applicable for 14-26-08.00-UG-U05-STD-HEL-04 BSP version.

- **New Features**

- **Bluetooth:**
 - Extend the support of Smart leash feature for the new Device Guardian package.

- **OSX:**

- Access Manager – System settings access provides a new admin configuration to add “Network settings” as part of reduced settings.
- **WLAN:**
 - Enabled Support to allow connection with TLS v1.3.
- **Audio**
 - Added support for MDM to launch ZVC using remapped key with intent broadcast.
 - Added support to display ZVC UI in French(Canada).
 - Added support for MDM to handle mute and vibrate usage enable & disable separately.
- **WWAN**
 - Cellular Insight (CIS) feature implemented.
 - IMS Roaming disabled for Verizon, AT&T & Telus.
- **Scanner Framework:**
 - **Free-Form OCR Improvements:** Developers can set default Region of Interest (ROI) frame sizes as a percentage of width and height and enable “Auto-Remember Resize” to retain user-adjusted ROI sizes for subsequent sessions.
 - **BT Pairing Utility Enhancement:** Added French translation to the Bluetooth (BT) Pairing Utility for improved accessibility.
 - **SE55 Firmware Update:** Included SE55 firmware version PAAFNS00-002-R01, which has the support for new LED part and improved ranging algorithm.
- **DataWedge**
 - DataWedge Intent API now supports custom notifications, allowing users to define specific configurations for LED patterns, beep sounds, and vibration sequences on supported RS5100, RS6000, and RS6100 Bluetooth scanners.
 - Added support for double short burst and long burst vibrations on connected RS5100, RS6000, and RS6100 Bluetooth scanners via the DataWedge Notify Intent API.
- **Zebra License Manager Application:**
 - Zlicensemgr apk 14.0.50.5.0.3 with Badge ID activation support has been integrated.
- **Resolved Issues**
 - SPR52847 - Resolved an issue wherein device gets disconnected after ~8 hr of constant connection using Fast roam.
 - SPR56202 - Resolved an issue wherein external keyboard languages are not setting correctly through StageNow.
 - SPR55465 - Resolved an issue wherein device fails to enroll while connecting to Wi-Fi network without requiring a Root CA or domain name.
 - SPR55604 - Resolved an issue wherein scanner stops working in presentation mode due to overheating.
 - SPR54787 - Resolved an issue wherein the initial 10sec of VOIP call was muffled.
 - SPR55548 - Resolved an issue wherein GPS data was not accurate.
 - SPR55368 - Resolved an issue wherein display size settings was not working as expected when applied via stage now.
 - SPR54877 - Added support for Secondary BLE to enable tracking of devices in Powered Off state.
 - SPR55800 - Resolved an issue wherein WFW is not able to access host on different subnet.
 - SPR54357 - Resolved an issue wherein external scanner was intermittently not working when ET45 was docked in the cradle.

- SPR54624 - Resolved an issue wherein Imager's Aimer is not shown in Free-Form image capture mode.
- SPR56272 - Resolved an issue wherein certain texts were not translated in Japanese language within Datawedge.

- **Usage Notes**

- Download latest [ZLicenseMgr APK](#) (15.0.4 or above) from Zebra's official support site (available from 2nd week of August 2025) and upgrade on your device on top of integrated version of ZLicenseMgr apk (14.0.50) so this will solve issue mentioned below:
 - SPR-57604 – Resolved an issue wherein Enterprise Browser v5.0.0.13 - Randomly displaying 'Device clock check failed.'

LifeGuard Update 14-26-08.00-UG-U05

- LifeGuard Update 14-26-08.00-UG-U05 contains security updates.
- This LG Delta Update package is applicable for 14-26-08.00-UG-U02-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-26-08.00-UG-U02

- LifeGuard Update 14-26-08.00-UG-U02 contains security updates.
- This LG Delta Update package is applicable for 14-26-08.00-UG-U00-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-26-08.00-UG-U00

- LifeGuard Update 14-26-08.00-UG-U00 contains security updates and bug fixes.
- This LG Delta Update package is applicable for 14-23-05.00-UG-U05-STD-HEL-04 BSP version.

○ **New Features**

○ **Restriction for skip setup wizard**

- Due to new mandatory privacy requirements from Google, the Setup Wizard Bypass feature has been discontinued on devices running Android 13 and later. Consequently, it is now restricted to skip the Setup Wizard screen, and the StageNow barcode will not function during the Setup Wizard, displaying a toast message stating “Not supported.”
- If the Setup Wizard has already been completed and its data was configured to persist on the device in the past, there is no need to repeat this process following an Enterprise Reset.
- For more details, please refer to the Zebra FAQ documentation:
<https://techdocs.zebra.com/zebradna/latest/faq/#setupwizardsuw>

○ **Bluetooth:**

- Admin configuration support to disable Bluetooth Profiles.

○ **MX 14.0:**

- App Manager adds the ability to
 - Use the App Feature parameter to automatically launch an app or reboot the device after installation.
- Bluetooth Manager adds the ability to:
 - Set individual Bluetooth Profiles as active or inactive.
- Display Manager adds the ability to
 - Control the Secondary Monitor Auto-rotation when a device is placed in a cradle connected to a monitor.
 - Specify a video file in the Screen Saver Path for display on the device.
- License Manager adds the ability to:
 - Perform licensing actions on non-legacy Zebra licenses.
 - Perform device licensing actions based on License Action type.
 - Perform BadgeID licensing based on Server Type.
- UI Manager adds the ability to:
 - Select a Navigation Method for switching between screens on a device.
 - Control Color Inversion on the device.
 - Control TalkBack feature, which speaks words displayed on the device screen.
- KeyMapping Manager adds the ability to
 - Configure Double-trigger Mode to launch an app or activity.

○ **MX 14.1:**

- Display Manager adds the ability to
 - Control display of the two-line clock on the Android lock-screen clock.

○ **Resolved Issues**

- SPR55016 - Resolved an issue to remap a key with flashlight application
- SPR54952 - Resolved an issue where, ZAMS and FFD, when enabled /used simultaneously, one/both become non-functional.
- SPR54744 - Resolved an issue where in the free fall detection (FFD) feature is not functional.

- SPR54688 – Resolved an issue to support for device locked orientation persistence during device lock/unlock scenario.
- SPR55563 - Resolved an issue wherein Fix has been implemented to address the crash by programmatically correcting the database schema in Quickstep app on A11 to A14 OTA scenario.

- **Usage Notes**

- None

LifeGuard Update 14-23-05.00-UG-U05

- LifeGuard Update 14-23-05.00-UG-U05 contains security updates.
- This LG Delta Update package is applicable for 14-23-05.00-UG-U03-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-23-05.00-UG-U03

- LifeGuard Update 14-23-05.00-UG-U03 contains security updates.
- This LG Delta Update package is applicable for 14-23-05.00-UG-U00-STD-HEL-04 BSP version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 14-23-05.00-UG-U00

- LifeGuard Update 14-23-05.00-UG-U00 contains security updates, bug fixes and SPRs.

- **New Features**

- Zebra is using Play Auto Installs (PAI) to support server-side configurations for installation of few GMS applications.
Google meet and Drive applications are installed as part of the end-user out-of-box experience. The above-mentioned applications are also installed as part of OS Upgrade from any of the previous OS versions to Android 14.
Enterprise use-cases like DO enrollment, Skip setup wizard will also have the abovementioned GMS applications installed as part of the end-user experience.
The above-mentioned GMS applications will be installed on the device after internet connection is enabled on the device.
After PAI has installed the above-mentioned GMS applications and if the user uninstalls any of them, such uninstalled applications will be re-installed back on next device reboot.
- The Hotseat home screen “Phone” icon has been replaced by the “Files” icon (for Wi-Fi-only devices).
- The split-screen feature on Tablet devices allows you to view two apps simultaneously.
- Users can select a portion of available device storage to be used as system RAM. This feature can be turned ON/OFF by the device admin only. Please refer to <https://techdocs.zebra.com/mx/powermgr/> for more details.
- Added support for DHCP Option 119, which will work only on managed devices over WLAN, and the WLAN profile should be created by the device owner.
- Added support to control BLE scan based on the application package.
- Added support for an RSSI filter for BLE scan based on the application package.
- Added support for 1x authentication in ethernet.
- Support for Cross AKM Roam and EAP TLS 1.3
- Wi-Fi Direct enhancements
- MC9300- Added support to improve battery life cycle for new battery (BT-000371-A0).

Scanning Features

- FS40 (SSI Mode) Scanner Support with DataWedge.
- Expose the GS1 DataBar Security Level settings.
- New Configurable Focus Parameters offered for devices with SE55 Scan Engines.
- SPR 53388: Firmware Update for SE55(PAAFNS00-001-R09) Scan Engine with Critical bug fixes, and performance enhancements.
- Added support for Regular Expression checking in Free-Form OCR and Picklist + OCR workflows.

○ Usage Notes

- Compatible with new Power Amplifier (PA) hardware (**SKY77652**). WWAN SKUs manufactured after November 25, 2024, will have this new PA component and will not be allowed to downgrade below the following Android images: A13 image 13-34-31.00-TG-U00-STD, A11 image 11-54-19.00-RG-U00-STD, A10 image 10-63-18.00-QG-U00-STD and A8 image 01-83-27.00-OG-U00-STD.
- Existing customers can upgrade to A14 with data persistence using one of the following methods.
 - a) Using FDE-FBE conversion package ([FDE-FBE conversion package – SDM660 Upgrade Path](#))

Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	14-38-04.00-UG-U00-STD-HEL-04
Android Version	14
Security Patch level	Feb 01, 2026
Component Versions	Please see Component Versions under Addendum section

Device Support

Please see device compatibility details under Addendum Section.

Known Constraints

- Dessert Upgrade to A14ss will have Enterprise reset because of Encryption change from FDE to FBE.
- Customers who upgrade from A10/A11 to A13 without FDE-FBE conversion package or EMM persistence will result in data wipe.
- Dessert upgrade from A10, A11 to A13 can be done with UPL with reset command. Oreo reset command is not supported.
- EMM supporting persistence feature (primarily Airwatch/SOTI) will only work while migrating from A11 to A13 and A11 to A14.
- This software does not support Mifare ultralight 64 bytes/512-bit NFC card

Important Links

- [SDM660 A14 OS Update instructions](#)
- [FDE-FBE conversion package – SDM660 Upgrade Path](#)
- [Zebra Techdocs](#)
- [Developer Portal](#)

Addendum

Device Compatibility

This software release has been approved for use on the following devices.

Device Family	Part Number	Device Specific Manuals and Guides
---------------	-------------	------------------------------------

MC3300ax	MC330X-SJ2EG4NA MC330X-SJ3EG4NA MC330X-SJ4EG4NA MC330X-SJ2EG4RW MC330X-SJ3EG4RW MC330X-SJ4EG4RW MC330X-SA2EG4NA MC330X-SA3EG4NA MC330X-SA4EG4NA MC330X-SA2EG4RW MC330X-SA3EG4RW MC330X-SA4EG4RW MC330X-SA3EG4IN MC330X-SA4EG4IN MC330X-SJ3EG4IN MC330X-SJ4EG4IN MC330X-SA3EG4TR MC330X-SA4EG4TR MC330X-SE2EG4NA MC330X-SE3EG4NA MC330X-SE4EG4NA MC330X-SE2EG4RW MC330X-SE3EG4RW MC330X-SE4EG4RW MC330X-SG2EG4NA MC330X-SG3EG4NA MC330X-SG4EG4NA MC330X-SG2EG4RW MC330X-SG3EG4RW MC330X-SG4EG4RW MC330X-SG3EG4IN MC330X-SG3EG4TR MC330X-SG4EG4TR MC330X-GJ4EG4NA-UP MC330X-GJ4EG4RW-UP	MC330X-GJ2EG4NA MC330X-GJ3EG4NA MC330X-GJ4EG4NA MC330X-GJ2EG4RW MC330X-GJ3EG4RW MC330X-GJ4EG4RW MC330X-GJ3EG4IN MC330X-GJ4EG4IN MC330X-GE2EG4NA MC330X-GE3EG4NA MC330X-GE4EG4NA MC330X-GE2EG4RW MC330X-GE3EG4RW MC330X-GE4EG4RW MC330X-GE3EG4IN MC330X-GE4EG4IN MC330X-GJ3EG4RW01 MC330X-GJ3EG4NA01 MC330X-GJ3EG4IN01 MC330X-GJ3BG4IN01 MC330X-GJ3BG4RW01 MC330X-GJ3BG4NA01 MC330X-SJ3BG4RW MC330X-GE4BG4RW MC330X-GE3BG4RW MC330X-GJ3BG4RW MC330X-GJ4BG4RW MC330X-SJ4BG4NA MC330X-GE2BG4RW MC330X-GE4BG4NA MC330X-GJ4BG4NA MC330X-GJ2BG4RW MC330X-GE3BG4NA MC330X-GE4EG4NA-UP MC330X-GE4EG4RW-UP	MC3300ax Home Page
MC20	MC200A-GA2S40JP		MC20 Home Page
RZ-H27X	RZ-H271		MC20 Home Page
CC600	CC600-5-3200LNNA CC600-5-3200LNWW	CC600-5-3200LNIN	CC600 Home Page
CC6000	CC6000-10-3200LCWW CC6000-10-3200PCWW CC6000-10-3200LCNA CC6000-10-3200NLCNA	CC6000-10-3200PCNA CC6000-10-3200LNNA CC6000-10-3200NLCWW	CC6000 Home Page
EC30	EC300K-1SA2ANA EC300K-1SA2AA6 EC300K-1SA2AIA	KT-EC300K-1SA2BNA-10 KT-EC300K-1SA2BA6-10	EC30 Home Page
EC50	EC500K-01B132-NA	EC500K-01B243-A6	EC50 Home Page

	EC500K-01B242-NA EC500K-01B243-NA EC500K-01D141-NA EC500K-01B112-NA EC500K-01B222-NA EC500K-01B223-NA EC500K-01D121-NA EC500K-01B112-IA EC500K-01B112-TR EC500K-01B112-XP EC500K-01D121-IA	EC500K-01D141-A6 EC500K-01B132-A6 EC500K-01B242-A6 EC500K-01B112-A6 EC500K-01B222-A6 EC500K-01B223-A6 EC500K-01D121-A6 EC500K-01B223-IA EC500K-01B223-TR EC500K-01B223-XP EC500K-01D121-TR EC500K-01D121-XP	
ET51	ET51CE-G21E-00A6 ET51CE-G21E-00IA ET51CE-G21E-00NA ET51CE-G21E-SFA6 ET51CE-G21E-SFIA	ET51CE-G21E-SFNA ET51CT-G21E-00A6 ET51CT-G21E-00IA ET51CT-G21E-00NA	ET51 Home Page
L10A	RTL10B1-xxxxxxxxxNA (North America) RTL10B1-xxAxxX0x00A6 (ROW) Note: 'x' Stands for wild card for different configurations	RTL10B1-xxAxxX0x00IN (India)	L10A Home Page
MC2200	MC220K-2A3S3RW MC220K-2B3E3RW MC220K-2B3S3IN MC220K-2B3S3NA	MC220K-2B3S3RW MC220K-2B3S3TR MC220K-2B3S3XP	MC2200 Home Page
MC2700	MC27AK-2B3S3NA MC27AK-4B3S3NA MC27BK-2B3S3ID MC27BK-2B3S3IN MC27BK-2B3S3RW	MC27BK-2B3S3TR MC27BK-2B3S3XP MC27BK-4B3S3RW MC27BK-2B3E3RW	MC2700 Home Page
MC3300x	MC330L-GE2EG4NA MC330L-GE2EG4RW MC330L-GE3EG4IN MC330L-GE3EG4NA MC330L-GE3EG4RW MC330L-GE4EG4IN MC330L-GE4EG4NA MC330L-GE4EG4RW MC330L-GJ2EG4NA MC330L-GJ2EG4RW MC330L-GJ3EG4IN MC330L-GJ3EG4NA MC330L-GJ3EG4RW MC330L-GJ4EG4IN MC330L-GJ4EG4NA MC330L-GJ4EG4RW	MC330L-SC2EG4NA MC330L-SC2EG4RW MC330L-SC3EG4NA MC330L-SC3EG4RW MC330L-SC4EG4NA MC330L-SC4EG4RW MC330L-SE2EG4NA MC330L-SE2EG4RW MC330L-SE3EG4NA MC330L-SE3EG4RW MC330L-SE4EG4NA MC330L-SE4EG4RW MC330L-SG2EG4NA MC330L-SG2EG4RW MC330L-SG3EG4IN MC330L-SG3EG4NA	MC3300x Home Page

	<p>MC330L-GL2EG4NA MC330L-GL2EG4RW MC330L-GL3EG4IN MC330L-GL3EG4NA MC330L-GL3EG4RW MC330L-GL4EG4IN MC330L-GL4EG4NA MC330L-GL4EG4RW MC330L-RC2EG4NA MC330L-RC2EG4RW MC330L-RC3EG4NA MC330L-RC3EG4RW MC330L-RC4EG4NA MC330L-RC4EG4RW MC330L-RL2EG4NA MC330L-RL2EG4RW MC330L-RL3EG4NA MC330L-RL3EG4RW MC330L-RL4EG4NA MC330L-RL4EG4RW MC330L-SA2EG4NA MC330L-SA2EG4RW MC330L-SA3EG4IN MC330L-SA3EG4NA MC330L-SA3EG4RW MC330L-SA3EG4TR MC330L-SA4EG4IN MC330L-SA4EG4NA MC330L-SA4EG4RW MC330L-SA4EG4TR</p>	<p>MC330L-SG3EG4RW MC330L-SG3EG4TR MC330L-SG4EG4NA MC330L-SG4EG4RW MC330L-SG4EG4TR MC330L-SJ2EG4NA MC330L-SJ2EG4RW MC330L-SJ3EG4IN MC330L-SJ3EG4NA MC330L-SJ3EG4RW MC330L-SJ4EG4IN MC330L-SJ4EG4NA MC330L-SJ4EG4RW MC330L-SK2EG4NA MC330L-SK2EG4RW MC330L-SK3EG4NA MC330L-SK3EG4RW MC330L-SK4EG4NA MC330L-SK4EG4RW MC330L-SL2EG4NA MC330L-SL2EG4RW MC330L-SL3EG4NA MC330L-SL3EG4RW MC330L-SL4EG4NA MC330L-SL4EG4RW MC330L-SM2EG4NA MC330L-SM2EG4RW MC330L-SM3EG4NA MC330L-SM3EG4RW MC330L-SM4EG4NA MC330L-SM4EG4RW</p>	
MC3300xR	<p>MC333U-GJ2EG4EU MC333U-GJ2EG4IL MC333U-GJ2EG4JP MC333U-GJ2EG4US MC333U-GJ3EG4EU MC333U-GJ3EG4US MC333U-GJ4EG4EU MC333U-GJ4EG4IN MC333U-GJ4EG4JP MC333U-GJ4EG4SL MC333U-GJ4EG4TH MC333U-GJ4EG4US MC333U-GJ4EG4WR MC339U-GE2EG4EU MC339U-GE2EG4JP MC339U-GE2EG4US MC339U-GE2EG4WR MC339U-GE3EG4EU</p>	<p>MC339U-GE3EG4US MC339U-GE4EG4EU MC339U-GE4EG4IN MC339U-GE4EG4JP MC339U-GE4EG4TH MC339U-GE4EG4US MC339U-GE4EG4WR MC339U-GF2EG4EU MC339U-GF2EG4US MC339U-GF3EG4EU MC339U-GF3EG4TH MC339U-GF3EG4US MC339U-GF4EG4EU MC339U-GF4EG4SL MC339U-GF4EG4TH MC339U-GF4EG4US MC339U-GF4EG4WR</p>	<p>MC3300xR Home Page</p>
MC93	<p>MC930B-GSXXG4XX MC930P-GSXXG4XX MC930P-GFXXG4XX</p>	<p>MC930B-GSXXG4NA-XX MC930P-GSXXG4NA-XX</p>	<p>MC9300 Home Page</p>

	Note: 'x' Stands for wild card for different configurations		
TC21	TC210K-01A222-A6 TC210K-01A242-A6 TC210K-01D221-A6 TC210K-01D241-A6 TC210K-01B212-A6 TC210K-01B232-A6 TC210K-01A422-A6 TC210K-01A442-A6 TC210K-0HD224-A6 TC210K-0HB224-A6 TC210K-0HB222-A6 TC210K-01A423-A6 TC210K-0JB224-A6 TC210K-01B422-NA TC210K-01A222-NA TC210K-01D221-NA TC210K-01D241-NA TC210K-0JD224-NA TC210K-0JB224-NA TC210K-01A242-NA TC210K-01A442-NA TC210K-01A222-A6P TC210K-01A422-A6P	TC210K-01A423-NA TC210K-0HD224-NA TC210K-0HB224-NA TC210K-0HB222-NA TC210K-01A422-NA TC210K-0HB224-IA TC210K-01A222-IA TC210K-01A242-IA TC210K-01A442-IA TC210K-01A422-IA TC210K-01B212-IA TC210K-01B232-IA TC210K-01A423-IA TC210K-01B232-TR TC210K-01B212-TR TC210K-01D221-TR TC210K-01D241-TR TC210K-0HD224-FT TC210K-01B212-XP TC210K-01B212-NA TC210K-01B232-NA TC210K-01A423-A6P TC210K-01A423-NAP	TC21 Home Page
TC21 HC	TC210K-0HD224-NA KT-TC210K-0HD224-FT TC210K-0HD224-A6 TC210K-0HB224-A6 TC210K-0JB224-A6 TC210K-0JD224-NA TC210K-0JB224-NA TC210K-0HB224-NA TC210K-0HB222-NA TC210K-0HB224-IA TC210K-0HB222-NA KT-TC210K-0HD224-PTTP1-NA KT-TC210K-0HD224-PTTP2-NA KT-TC210K-0HD224-PTTP1-FT KT-TC210K-0HD224-PTTP2-FT KT-TC210K-0HD224-PTTP1-A6 KT-TC210K-0HD224-PTTP2-A6	KT-TC210K-0HB224-PTTP1-A6 KT-TC210K-0HB224-PTTP2-A6 KT-TC210K-0HD224-WFC1-NA KT-TC210K-0HD224-WFC2-NA KT-TC210K-0HD224-WFC1-FT KT-TC210K-0HD224-WFC2-FT KT-TC210K-0HD224-WFC1-A6 KT-TC210K-0HD224-WFC2-A6 KT-TC210K-0HB224-WFC1-A6 KT-TC210K-0HB224-WFC2-A6 TC210K-0JB224-A6P TC210K-0JB224-NAP	TC21 Home Page
TC26	TC26BK-11A222-A6 TC26BK-11A242-A6 TC26BK-11A422-A6	TC26AK-11A442-NA TC26BK-11A222-IA TC26BK-11A242-IA	TC26 Home Page

	TC26BK-11A423-A6 TC26BK-11A442-A6 TC26BK-11B212-A6 TC26BK-11B232-A6 TC26BK-11B412-A6 TC26BK-11D221-A6 TC26BK-11D241-A6 TC26BK-11D421-A6 TC26BK-21D221-A6 TC26BK-21A222-A6 TC26BK-1HB224-A6 TC26BK-1HD224-A6 TC26BK-1JB224-A6 TC26BK-21A442-A6 TC26AK-11A222-NA TC26AK-11A242-NA TC26AK-11A422-NA TC26AK-11A423-NA TC26AK-11B212-NA TC26AK-11B232-NA TC26AK-11D221-NA TC26AK-11D241-NA TC26AK-1HB222-NA TC26AK-1HB224-NA TC26AK-1HD224-NA TC26AK-1JD224-NA TC26BK-11A222-A6P TC26BK-11A422-A6P TC26BK-11A423-A6P TC26BK-21A422-A6P	TC26BK-11A442-IA TC26BK-11B212-IA TC26BK-11B232-IA TC26BK-21A222-IA TC26BK-1HB224-IA TC26BK-11D221-IA TC26BK-11A222-BR TC26BK-11A242-BR TC26BK-11A422-BR TC26BK-11A423-BR TC26BK-11A442-BR TC26BK-11B212-BR TC26BK-11B232-BR TC26BK-11D221-BR TC26BK-11D241-BR TC26BK-1HB224-BR TC26DK-11B212-TR TC26DK-11B232-TR TC26BK-11B212-TR TC26BK-11B232-TR TC26BK-11B212-ID TC26BK-11A222-ID TC26BK-11B212-XP TC26AK-1HD224-FT TC26AK-21A222-NA TC26AK-1JB224-NA TC26AK-11A423-NAP TC26EK-21A222-NAP TC26DK-11A422-IDP	
TC26 HC	TC26BK-1HD224-A6 TC26BK-1HB224-A6 TC26BK-1HB224-BR TC26AK-1HD222-NA TC26BK-1HB224-IA TC26AK-1JB224-NA TC26BK-1JB224-A6 TC26AK-1HD224-NA TC26AK-1HB224-NA KT-TC26AK-1HD224-FT TC26AK-1HB222-NA TC26AK-1JD224-NA KT-TC26BK-1HD224-PTTP1-A6 KT-TC26BK-1HD224-PTTP2-A6 KT-TC26BK-1HB224-PTTP1-A6 KT-TC26BK-1HB224-PTTP2-A6 KT-TC26AK-1HD224-PTTP1-NA TC26BK-1JB224-A6P	KT-TC26AK-1HD224-PTTP2-NA KT-TC26AK-1HD224-PTTP1-FT KT-TC26AK-1HD224-PTTP2-FT KT-TC26AK-1HD224-WFC1-NA KT-TC26AK-1HD224-WFC2-NA KT-TC26AK-1HD224-WFC1-FT KT-TC26AK-1HD224-WFC2-FT KT-TC26BK-1HD224-WFC1-A6 KT-TC26BK-1HD224-WFC2-A6 KT-TC26BK-1HB224-WFC1-A6 KT-TC26BK-1HB224-WFC2-A6 TC26AK-1JB224-NAP	TC26 Home Page

TC52	TC520K-1PEZU4P-A6 TC520K-1PEZU4P-NA	TC520K-1PEZU4P-IA TC520K-1PEZU4P-FT	TC52 Home Page
TC52 AR1337 Camera	TC520K-1PFZU4P-A6	TC520K-1PFZU4P-NA	TC52 Home Page
TC52 HC	TC520K-1HEZU4P-NA TC520K-1HEZU4P-EA TC520K-1HEZU4P-A6 TC520K-1HEZU4P-FT TC520K-1HEZU4P-IA KT-TC520K-1HCMH6P- PTT1-NA KT-TC520K-1HCMH6P- PTT2-NA KT-TC520K-1HCMH6P- PTT1-FT KT-TC520K-1HCMH6P- PTT2-FT KT-TC520K-1HCMH6P- PTT1-A6 KT-TC520K-1HCMH6P- PTT2-A6 KT-TC520K-1HEZU4P- WFC1-NA KT-TC520K-1HEZU4P- WFC2-NA KT-TC520K-1HEZU4P- WFC1-FT KT-TC520K-1HEZU4P- WFC2-FT KT-TC520K-1HEZU4P- WFC1-A6 KT-TC520K-1HEZU4P- WFC2-A6 KT-TC52-1HEZWFC1-NA	KT-TC520K-1HEZU4P- PTT1-FT KT-TC520K-1HEZU4P- PTT2-FT KT-TC520K-1HEZU4P- PTT1-A6 KT-TC520K-1HEZU4P- PTT2-A6 KT-TC520K-1HEZU4P- WFC1-NA KT-TC520K-1HEZU4P- WFC2-NA KT-TC520K-1HEZU4P- WFC1-FT KT-TC520K-1HEZU4P- WFC2-FT KT-TC520K-1HEZU4P- WFC1-A6 KT-TC520K-1HEZU4P- WFC2-A6 KT-TC52-1HEZWFC1-NA	TC52 HC Home Page
TC52x	TC520K-1XFMU6P-NA TC520K-1XFMU6P-A6 TC520K-1XFMU6P-TK	TC520K-1XFMU6P-FT TC520K-1XFMU6P-IA	TC52x Home Page
TC52x HC	TC520K-1HCMH6P-NA TC520K-1HCMH6P-FT TC520K-1HCMH6P-A6 TC520K-1HCMH6P-PTTP1- NA TC520K-1HCMH6P-PTTP2- NA TC520K-1HCMH6P-PTTP1- FT TC520K-1HCMH6P-PTTP2- FT TC520K-1HCMH6P-PTTP1- A6	TC520K-1HCMH6P-PTTP2- A6 TC520K-1HCMH6P-WFC1- NA TC520K-1HCMH6P-WFC2- NA TC520K-1HCMH6P-WFC1- FT TC520K-1HCMH6P-WFC2- FT TC520K-1HCMH6P-WFC1- A6 TC520K-1HCMH6P-WFC2- A6 KT-TC52X-1HCMWFC1-NA	TC52x Home Page
TC52AX	TC520L-1YFMU7P-NA TC520L-1YFMU7T-NA TC520L-1YLMU7T-NA	TC520L-1YFMU7P-A6 TC520L-1YFMU7T-A6 TC520L-1YLMU7T-A6	TC52ax Home Page
TC52AX HC	TC520L-1HCMH7T-NA	TC520L-1HCMH7T-A6	TC52ax Home Page

	TC520L-1HCMH7P-NA TC520L-1HCMH7P-FT	TC520L-1HCMH7P-A6 TC520L-1HCMH7T-FT	
TC57	TC57HO-1PEZU4P-A6 TC57HO-1PEZU4P-IA TC57HO-1PEZU4P-NA TC57HO-1PEZU4P-XP	TC57HO-1PEZU4P-BR TC57HO-1PEZU4P-ID TC57HO-1PEZU4P-FT TC57HO-1PEZU4P-SKT	TC57 Home Page
TC57 AR1337 Camera	– TC57HO-1PFZU4P-A6	TC57HO-1PFZU4P-NA	TC57 Home Page
TC57x	TC57HO-1XFMU6P-A6 TC57HO-1XFMU6P-BR TC57HO-1XFMU6P-IA TC57HO-1XFMU6P-FT	TC57HO-1XFMU6P-ID TC57JO-1XFMU6P-TK TC57HO-1XFMU6P-NA	TC57X Home Page
TC72	TC720L-0ME24B0-A6 TC720L-0ME24B0-NA TC720L-0ME24B0-BR TC720L-0ME24B0-IA TC720L-1ME24B0-A6 TC720L-1ME24B0-NA	TC720L-0ME24B0-TN TC720L-0ME24B0-FT TC720L-0MJ24B0-A6 TC720L-0MJ24B0-NA	TC72 Home Page
TC72 AR1337 Camera	– TC720L-0MK24B0-A6 TC720L-0MK24B0-NA	TC720L-0ML24B0-A6 TC720L-0ML24B0-NA	TC72 Home Page
TC77	TC77HL-5ME24BG-A6 TC77HL-5ME24BD-IA TC77HL-5ME24BG-FT (FIPS_SKU) TC77HL-7MJ24BG-A6 TC77HL-5ME24BD-ID TC77HL-5ME24BG-EA TC77HL-5ME24BG-NA TC77HL-7ME24BG-NA TC77HL-7ML24BG-A6	TC77HL-5MG24BG-EA TC77HL-6ME34BG-A6 TC77HL-5ME24BD-BR TC77HL-5MJ24BG-A6 TC77HL-5MJ24BG-NA TC77HL-7MJ24BG-NA TC77HL-5MG24BG-A6 TC77HL-5ME24BD-TN TC77HL-7ME24BG-A6	TC77 Home Page
TC77 AR1337 Camera	– TC77HL-5MK24BG-A6 TC77HL-5MK24BG-NA	TC77HL-5ML24BG-A6 TC77HL-5ML24BG-NA	TC77 Home Page
TC8300	TC83B0-x005A510NA TC83B0-x005A61CNA TC83BH-x205A710NA TC83B0-x005A510RW TC83B0-x005A61CRW TC83BH-x205A710RW TC83B0-x005A510IN TC83B0-x005A61CIN TC83BH-x205A710IN TC83BH-x206A710NA	TC83BH-x206A710RW TC83B0-4005A610NA TC83B0-4005A610RW TC83B0-4005A610IN TC83B0-5005A610NA TC83B0-5005A610RW TC83B0-5005A610IN TC83B0-x005A510TA TC83BH-x205A710TA	TC8300 Home Page

	Note: 'x' Stands for wild card for different configurations		
VC8300 8"	VC83-08FOCABAABA-I VC83-08FOCQBAABA-I VC83-08FOCQBAABANA VC83-08SOCABAABA-I	VC83-08SOCQBAABA-I VC83-08SOCQBAABAIN VC83-08SOCQBAABANA	VC8300 Home Page
VC8300 10"	VC83-10FSRNBAABA-I VC83-10FSRNBAABANA VC83-10SSCNBAABA-I	VC83-10SSCNBAABANA VC83-10SSCNBAABATR	
WT6300	WT63B0-TS0QNERW WT63B0-TS0QNENA WT63B0-TS0QNE01 WT63B0-TX0QNERW WT63B0-TX0QNENA	WT63B0-KS0QNERW WT63B0-KS0QNENA WT63B0-KX0QNERW WT63B0-KX0QNENA WT63B0-TS0QNETR	WT6300 Home Page

Component Versions

Component / Description	Version
Linux Kernel	4.19.157-perf
GMS	14_202408
AnalyticsMgr	10.0.0.1008
Android SDK Level	34
Audio	0.1.0.0
Battery Manager	1.4.8
Bluetooth Pairing Utility	6.4
Camera	2.0.002(52-00)
DataWedge	15.0.54
License Manager and License Agent	version 6.1.7 and version 15.0.4.5.0.3
Files	14-11531109
MXMF	15.1.0.20
NFC	NFC_NCIHALx_AR18C0.d.2.0
OEMInfo	9.0.1.684

OSX	SDM660.140.14.13.12
RXlogger	14.0.13.74
Scanning Framework	43.63.12.1
StageNow	13.4.0.0
Zebra device manager	15.1.0.20
Zebra Bluetooth	14.8.1
Zebra Volume Control	3.0.0.123
Zebra Data Service	14.0.1.1273
WLAN	FUSION_QA_2_1.0.0.038_U
Android System WebView	142.0.7444.171
Chrome	142.0.7444.171
Showcase App	1.0.55

Revision History

Rev	Description	Date
1.0	Initial release	February 27, 2026