


USB-C Dock, Dual Display 4K 60Hz HDMI, 6x USB, GbE, 100W PD


Product ID

196N-USBC-DOCK
196UE-USBC-DOCK


Front View



Side View



Rear View



*Product may vary from image

Component	Function
1 USB-A 5Gbps Ports	• Connect and/or charge USB Peripherals
2 USB-C 10Gbps Port with Charging	• Connect and/or charge a USB Peripheral • Supports USB 10Gbps and USB Power Delivery up to 15W
3 USB-C 10Gbps Port	• Connect and/or charge a USB Peripheral
4 Power Button	• Press and release to toggle Power on or off for the Docking Station
5 3x Lock Slots (Nano/Standard/Wedge)	• Connect a K-Slot, Nano, or Wedge Locking Device to deter theft of the Docking Station
6 Power Input	• Connect the Docking Station to a Power Source using the included Universal Power Adapter
7 USB-C Host Connection	• Connect to a USB-C Port on the Host Computer • Supports Power Delivery 3.0 for up to 100W Laptop Charging
8 HDMI Outputs	• Connect up to two HDMI Displays
9 Gigabit Ethernet Port	• Connect the Docking Station to a Network

Package Contents

- Docking Station x 1
- 3.3ft (1m) Host Cable x 1
- Universal Power Adapter x 1
- Product Documentation x 1

Requirements

For the latest manuals, product information, technical specifications, and declarations of conformance, please visit:

www.StarTech.com/196N-USBC-DOCK
www.StarTech.com/196UE-USBC-DOCK

- Computer x 1
- The host computer's USB-C port must support Power Delivery and DisplayPort Alt Mode for full docking station functionality.
- Video support and performance, such as the number of external displays, their resolution, and refresh rate, depend on the host computer and the performance of the video card or host port.

Installation

1. Connect the **Power Adapter** from an **AC Outlet**, to the **Power Input Port** on the **Docking Station**.
2. Connect a **Network Cable** from a **Network Port/Device** to the **Gigabit Ethernet Port** on the back of the **Docking Station**.
3. Connect **USB Devices** or **Peripherals** to the **USB-A** and **USB-C Ports** located on the front and rear of the **Docking Station**.
4. Connect up to two **HDMI Displays** to the **HDMI Outputs** on the back of the **Docking Station** using an **HDMI Cable** (sold separately).
5. Connect the included **3.3ft (1m) Host Cable** from the **USB-C Host Connection** on the back of the **Docking Station** to a **USB-C Port** on the **Laptop**.
6. Press the **Power Button** on the front to power on the **Docking Station**.
7. The **Host Computer** will automatically detect the **Docking Station** and install the required **Drivers**.

StarTech.com Ltd.
45 Artisans Crescent
London, Ontario
N5V 5E9
Canada

StarTech.com LLP
4490 South Hamilton
Road
Groveport, Ohio
43125
U.S.A.

StarTech.com Ltd.
Unit B, Pinnacle 15
Gowerton Road
Brackmills,
Northampton
NN4 7BW
United Kingdom

StarTech.com Ltd.
Siriusdreef 17-27
2132 WT Hoofddorp
The Netherlands

FR: startech.com/fr
DE: startech.com/de
ES: startech.com/es
NL: startech.com/nl
IT: startech.com/it
JP: startech.com/jp

